Work Orde Friday, April 16,												Page 1	
Revision ID:	D3911-5			Accept				ll III s	Setup	Start			
	Basket Stud Pl 4/20/2010 4/28/2010	Start Qty: 12.00 Req'd Qty: 12.00	\		Cust Item :	ID:				Stop			
Approvals:	Process Pla QC:	n:_ MF	Date: (0- 4-1 φ	Tooling: SPC (Y/N):		ate:		F	Run	Start Stop			
Sequence ID/ Work Center II)	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Rejo Qty		Reject Number	Insp. Stamp	
Draw Nbr	Rev	ision Nbr					- 1						
D3911	С												
100 Waterjet		Memo		0.00				R	(0-1	4-19			
FLOW CNC Waterje		Cut as per of Prog Rev:_ Dwg Rev:_	Č									\	
		Deburr as re		eburr =	7 mih	10/04	1/19				· U	3)	
110 		QC2- Inspect parts off n	nachine FAI/FAIB	0.00				R	10 -	4- K	١		
Quality Control		IVECNIAU										01	

Pho

Dart	Aeros	pace	Ltd
------	--------------	------	-----

1843	WORK ORDER CHANGES							
STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
生ルの	Took at +1 For acinspection template	5	10/04/19	41		5 10/04/19		
Ī	STEP	STEP PROCEDURE CHANGE Took at +1 For acinspecting template	STEP PROCEDURE CHANGE By Took at +1 For acinspectin template	STEP PROCEDURE CHANGE By Date Took at +1 For acinspecting template	STEP PROCEDURE CHANGE By Date Qty Took at +1 For acinspecting template	STEP PROCEDURE CHANGE By Date Qty Approval Chief Eng / Prod Mgr Took at +1 For accinspection template		

Part No: <u>D3911-5</u> PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
Resolution:	Disposition:	QA: N/C Closed:	Date:

NCR:	:	WORK ORDER NON-CONFORMANCE (NCR)											
		Description of NC		Corrective Action Section B		Verification	Annecial	Annuaral					
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector					
								-					
•													

								1					
								i					
								<u>.</u>					

Work Orde Friday, April 16												Page 2
Item ID: Revision ID:	D3911-5			Accept			S	Setup	Start			
Item Name:	Basket Stud I	Plate								Stop		
Start Date: Required Date: Reference:	4/20/2010 4/28/2010	Start Qty: 12.00 Req'd Qty: 12.00) 200121 (1818 1161 1161 1161 1 (1818) (1818 1161 1161	ii	Cust Item I Customer:	D:						
Approvals:	Process Pl	an:	Date:	Tooling: SPC (Y/N):		ate:		I	Run	Start Stop		
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp
QC Quality Control		QC8- Inspect parts - second . Memo	ond check	0.00 Scolarl	(%		·	(H))			·····
130 Packaging Packaging		Identify as per dwg & St	ock Location. <u>U95</u>	0.00		·	·		<u>f</u> e	1	ly/2	0 (17
140		QC21- Final Inspection	- Work Order Release	0.00							10/04	1204
QC Quality Control		Memo		0.00							MF	13078 -4-20

Dart Aerospace Ltd

W/O:			W	ORK ORDER CHAN	GES				· · · · · · · · · · · · · · · · · · ·	, ¥
DATE	STEP	PRO	PROCEDURE CHANGE					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	9 - -									
			The state of the s							
Part No	•	PAR #:	Fault Cat	egory:	NCR:	Yes N	lo DQ	\ :	_ Date:	
Resolution:			Dispositi	Disposition: QA: N/C Closed: [Date:		
NCR:			WORK ORI	DER NON-CONFORM	MANCE (NCR)				
DATE	STEP	Description of NC	Initial	Corrective Action Section B				ation	Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspector
										-
									:	
									-	
									i I	

- Picklist Print

Friday, April 16, 2010 1:09:44 PM

Work Order ID: 57843

Parent Item:

D3911-5

Parent Item Name:

Basket Stud Plate

Comments:

IPP RevA: new issue DD 09.11.17 verified by:EC

REV:B AS PER REV B 10-03-23 JLM VERIFIED BY:DD

IPP

Start Date: 4/20/2010

Required Date: 4/28/2010

Start Qty: 12.00

Required Qty: 12.00

Component Item ID/ Item Name

M304S11GA

Replacement Mfg/ Item ID Purch Purchased

Primary Item Location No

Last Location Route Seq ID 100

Unit of Oty on Measure Hand sf 20.2000

Remaining 0.3777

Qty Qty To Pick Issued 12,

Date Issued

Status

Page 1

304/316 0.125 Sheet

Warehouse

Loc Oty

Loc Code

13 10-4-19

Location

Main Warehouse

MAT19

112663

20.2

20.2

112063

Dart Aerospace Ltd

										
W/O:			WO	RK ORDER CHAN	GES					· ·
DATE	STEP	PRO	OCEDURE CHAN	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								i		
Part No		PAR #:								
Resolution:			Disposition	Disposition:						
NCR:			WORK ORDE	R NON-CONFORM	MANCE	(NCR)				
DATE	STEP	Description of NC	NC Corrective Action				Verification		Approval	Approval
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng)	Sign & Date	Sectio		Chief Eng	QC Inspector
										-
			·							
								4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		
										1

DART AEROSPACE LTD	Work Order:	57843
Description: BRSKET STUD PLATE	Part Number: T	3911-5
Inspection Dwg DS411 - 5 , Rev: C		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X First Article X Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Rejest	Method of Inspection	Comments
P61. Ø	1005 - 200, 4	131	8			
11/	1006-001	.)(a)	*			
	4010	375	*			
	th 010	, 066	8			
,375	Y010	,375	K			
1.67	4 .030	1.617	7			
,50	4_ 00	150	8			
1.000	4010	1,000	<i>'E</i>			
- 200	400	1500	75			
2.15	4 030	2,147	70			
1.000	4- 010	1.001	8			
,58	7030	,498	7			
æ. €	T03U	2.017	>			
,175	71010	.119	ঠ			
						:

Measured by: kg	Audited by:	Prototype Approval:	
Date: 10-4-19	Date: 1004/19	Date:	

Rev	Date	Change	Revised by	Approved
A		New Issue	KJ/JLM	



W/O:			W	ORK ORDER CHAN	GES				•	
DATE	STEP	PR	PROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
										
Part No	:	PAR #:	Fault Cat	egory:	NCR: Yes No DQA: Date:					
	Res	solution:	Dispositi	on:	QA: N/C C	A: N/C Closed:			Date:	
NCR:			WORK ORI	DER NON-CONFORM	IANCE (NC	R)				
DATE	STEP	Description of NC Section A			ction B	Verificat		n Approval	Approval	
			Initial Chief Eng	Action Description Chief Eng	Sign Date	& Secti		Chief Eng	QC Inspector	
									-	
						İ				